MR-1 CHECK OFF LIST FOR NON-CATEGORICAL COMPANIES

CRAFT TEXTILE

27220136-outlets 1 & 2

1.	MONTH OF NOVEMBER 1, 2008 THRU NOVEMBER 30,	2008		
2.	Is Outlet # (8 digit) Correct?	Y	N	N/A
3.	Is average Total flow-gal.day stated in space provided?	(y)	N	N/A
4.	Is max. Total flow-gal day stated in space provided?	(Y)	N	N/A
5.	Is method used to calculate water stated?	Y	N .	N/A
6.	Are number of working days stated?	(Jy)	N	N/A
7.	Are there any parameters which have exceeded PVSC Local Limits?	Y	N	N/A
8.	Is proper compliance/non-compliance statement provided?	(Y)	Ŋ	N/A
9.	Have correct number of samples been submitted?	Y	N	N/A
10.	Has PHC result been listed on MR-1 report?	Y	N	N/A
11.	Has sample number been reported in space provided?	Y	N	N/A
12.	Have all regulated parameters been listed on MR-1?	Y	N	N/A
13.	Has sample type been stated on MR-1?	(Y)	N	N/A
14.	Have all samples been taken during this reporting period?	(Y)	N	N/A
15.	Has NJDEPE certified lab been used	Y	N	N/A
16.	Have analytical results been submitted on copies of Laboratory stationery?	(Y)	N	N/A
17.	Have results been written in space designated on MR-1?	(Y	N	N/A
18.	Is correct method used to preserve samples stated on MR-1?	(Y)	N	N/A
19.	Has MR-1 been signed by authorized representative?	Y	N	N/A
20.	Has information been submitted on proper MR-1 form?	LY	N	N/A
21.	Remove Arsenic from report if sampling not required	Y	N	(N/A)

MR-1 CHECK OFF LIST FOR NON-CATEGORICAL COMPANIES

Craft Textile	27220136	
First Reviewer: comments or	n deficiencies complete	
Date Reviewed 1/19/09	Date sent to user	· · · · · · · · · · · · · · · · · · ·
Date due back	Reviewer c.y.m.	
Second review comments on	n deficiencies	
Date Reviewed	Date sent to user	
Date due back	Reviewer	
Date	Reviewer	

DEC - 3 2008

·chon

PRETREATMENT MONITORING REPORT

NAME:

Craft Textile Printing Co., Inc.

MAILING ADDRESS:

P.O. Box 2761, Paterson, NJ 07509-2761

Regulated Flow(gal/day)

Total Flow (gal/day)

FACILITY LOCATION:

44 Beech Street, Paterson, NJ 07501

Category & Subpart: 9999

OUTLET # 1

Contact Official: H.R. Casparian

Telephone # 973-278-3818

New Customer ID/Outlet ID: 27220136-1

Old Outlet Designation: 27400061

Average Maximum

N/A

35846

<u>39431</u>

 MONITORING PERIOD

 START
 END

 11/1/2008
 11/30/2008

 m/d/yr
 m/d/yr

Method Used:

Gallons in less 5% evap. divided by

production days in month (11)

Production Rate:

N/A

<u>Parameter</u>		Mass	or Concent	<u>ration</u>	# of Samples	Sample Type
		Mon Avg	<u>Maximum</u>	<u>Units</u>		Comp/Grab
Zinc	Sample Measurement	0.0374		mg/l	1	Comp
	Permit Requirement	1.67		mg/l		
Copper	Sample Measurement	0.218		mg/l	1	Comp
	Permit Requirement	.092/3.02		mg/l		
	Sample Measurement					
	Permit Requirement			1 1-3		
- 39	Sample Measurement					
	Permit Requirement		19			02021
	Sample Measurement		4		100	293031
	Permit Requirement				(2)	//
	Sample Measurement				100	-//
	Permit Requirement				100	172/2/
	Sample Measurement				8	1. =/ /
	Permit Requirement		46	7 18 19 2	1 23 8	章 8
	Sample Measurement		1000	-02	101 13	00
	Permit Requirement		(0)	4	13/18	
	Sample Measurement		100		10/ /02	
	Permit Requirement		10 V	41/	19	(<u> </u>
	Sample Measurement		0	AN 2009	165	
	Permit Requirement		LEHENS.	Input	18/	
	Sample Measurement		100	2010 Com.	1,39/	
	Permit Requirement		100	NE,	187	-
	Sample Measurement		1000	7 15 05 9		
	Permit Requirement			De la Company		
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					-
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					

PVSC Form MR-1 Rev: 4 6/87 P1

Certification of Non-Use if applicable (use additional sheets)

Compliance or non-compliance statement with compliance schedule for every parameter used:

ZN, CU < Local Limits:

N/A

ΖN < Threshold Values

> Local Limits: > Threshold Values:

CU

Craft Textile Printing Co., Inc., is in compliance with local limits.

Explain "Method for preserving samples:

Refrigerator until end of pumping, then nitric acid as a preservative to a pH less than 2.

I certify under penalty of law that this document and attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or the persons directly responsible for gathering the information, the information submitted is. to the best of my knowledge and belief, true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

403.6(a)(2)(ii) revised by 53 FR 40610. October 17, 1988

Signature of Principal

executive or authorized agent

H.R. Casparian-President Name-Title 12/1/2008

PVSC Form MR-1 Rev: 5 3/91 P2

EPA Request #: III.B.1.e.

PRETREATMENT MONITORING REPORT

NAME:

Craft Textile Printing Co., Inc.

MAILING ADDRESS:

P.O. Box 2761, Paterson, NJ 07509-2761

FACILITY LOCATION:

44 Beech Street, Paterson, NJ 07501

Category & Subpart: 9999

OUTLET#2

Contact Official: H.R. Casparian

Telephone # 973-278-3818

New Customer ID/Outlet ID: 27220136-2

END

11/30/2008

m/d/yr

Old Outlet Designation: 27400062

MONITORING PERIOD

START

11/1/2008

m/d/yr

Regulated Flow(gal/day)

Average Maximum

Total Flow (gal/day)

N/A 25084

27592

DEC

Method Used:

Gallons in less 5% evap. divided by production days in month (11)

Production Rate:

N/A

Parameter		Mass	or Concent	ration	# of Samples	Sample Type
		Mon Avg	<u>Maximum</u>	<u>Units</u>		Comp/Grab
Zinc	Sample Measurement	Mon Avg 0.0789		mg/l	1	Comp
	Permit Requirement	1.67		mg/l		
Copper	Sample Measurement	0.0511		mg/l	1	Comp
	Permit Requirement	.092/3.02		mg/l		
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement			02031-		
	Sample Measurement		65	755	53/	
	Permit Requirement		(0)		20	
	Sample Measurement		100	5 (2/	
	Permit Requirement		12	A A	0	
	Sample Measurement		S	1300	0	
	Permit Requirement		(2)	# 8	07	
	Sample Measurement		10	7 0	~	
	Permit Requirement		100		15	
	Sample Measurement		100	9/	010	
	Permit Requirement			59171912		
	Sample Measurement					
	Permit Requirement					
	Sample Measurement				1617 18	1920
	Permit Requirement			/	Dil	1
	Sample Measurement			/6		\$ 10/
	Permit Requirement			100	T	100
	Sample Measurement		No.	11	JAN	100
	Permit Requirement			0,0	2000	00
	Sample Measurement			(0)	Dollary april	6
	Permit Requirement			1	- Will De	,0
	Sample Measurement			/	5.	189/
	Permit Requirement				(6>)	+ 0E'0"

PVSC Form MR-1 Rev: 4 6/87 P1

Certification of Non-Use if applicable (use additional sheets) $\frac{N/A}{}$

Compliance or non-compliance statement with compliance schedule for every parameter used:

< Local Limits: ZN , CU

> Local Limits:

N/A

< Threshold Values ZN , CU

N, CU > Threshold Values:

N/A

Craft Textile Printing Co., Inc., is in compliance with local limits.

Explain "Method for preserving samples:

Refrigerator until end of pumping, then nitric acid as a preservative to a pH less than 2.

I certify under penalty of law that this document and attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or the persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

403.6(a)(2)(ii) revised by 53 FR 40610. October 17, 1988

Signature of Principal

executive or authorized agent

H.R. Casparian-President
Name-Title
12/1/2008
Date

PVSC Form MR-1 Rev: 5 3/91 P2

HOJECT NO.	074228	BILLING INFORMATION	POF:		STATE: ZIP:	PHONE	ANALYSIS			' '	COMMENTS IN	A-HCI B-HNO.	6					**					KENV BENEFIT OF THE SECOND OF	ant Cooler Yamp.	ED CLOVERNIGHT Shipmen Complete:	
CHEMTECH PHOJECT NO.	COC Number	CUENT	BILL TO:	ADDRESS:	CITY:	ATTENTION:					RESERVATIVES		3 4 5 6 7 8										SESSION INCLUDING COURIER DELIV	y: ☐ Compilant ☐ Non Compilant anal 4 oz jar tor percent solid.	}	COPY FINK - SAMPLER COPY
Mountainside, NJ 07092 Fax (908) 789-8922	-33	CLIENT PROJECT INFORMATION		1.OCATION:			FAX:	DATA DELIVERABLE INFORMATION	C) USEPA CLP C) New York Subo ASP "8"	O New York State ASP 'A'	11/2	SAMPLE COLLECTION FO	DATE THAE 5 1 2	11/50s North 2 XX	X X X Water 30/2/n								THE SAMPLES CHANGE POSSESSION INCLUDING COURIER DELIVERY	Conditions of bothers or coolers at receipt. D Compilent D MeCH extraction requires an additional 4 oz par for percent solid.	10	ETURN TO CLIENT YELLOW - CHEMTECH COPY
284 Sheffield Street, Mountainside,	D'ANAMA		TAS SOCIECTIVANE	The state of the s	07509 PROJECT MANAGER	е-mail:	PHONE		AYS.		C EOO FOR	SAMPLE			7								NO SEE DOOR MENTED BEI DU	INCENTION OF THE PROPERTY OF T	1305 RECENSION UP 37	WATE - CHENTECH COPY FOR RETUR
	CHAIN OF CUSTODY RECORD	MOINT INFORMATION	REPORT TO BE SENT TO	ישישישישיים איני	Pore 6 601	2	473-278-38.8 Ex 973-523-8177]§			PREAPPROVED TAT: CLYES CLNO STANDARD TURNARQUIND TIME IS 10 BUSINESS DAYS	PROJECT	SAMPLE IDENTIFICATION	Ourier He	İ	CAMPER TO		3- X-				3			ONTERIUE:	
	MAIN OF C			~	S	CUS: LA	ATTENTION 4713	PHONE.	FAX	HARD COPT:	PREAPPROVED TAT: STANDARD TURNARC	CHENTECH	SAMPLE	-		i 69	4	5.	10	7.	æi	ø;	1a.	RELIGIOS DE DES CONTRERENTES ON CONTRE CONTR	PETINOUISMENT	

Chemtech Consulting Group

Hit	Summary	Sheet
	SW-846	

					٠,					
SDG No.:	Z5300		25300							
Client:	Craft Textile Pri	nting		Project ID:	Permit Renewal 2008					
Sample ID Client ID:	- Client ID OUTLET1			Concentration	С	RDL	MDL	Units		
Z5300-01	OUTLETI	WATER	Copper	218		10.0	2.400	ug/L		
Z5300-01	OUTLET1	WATER	Zinc	37.4		20.0	4.800	ug/L		
Client ID:	OUTLET2									
Z5300-02	OUTLET2	WATER	Copper	51 .1		10.0	2.400	ug/L		
Z5300-02	OUTLET2	WATER	Zinc	78.9		20.0	4.800	ug/L		

JAUL DOWN DOX

NON USE CERTIFICATION MONITORING REPORT LOCAL LIMITS

NAME: CRA	FT TEXTILE						
MAILING ADDE	RESS:						
	ATION:						
	SUBPART PER			ЛТLET#: ə	7220136	-2	
	 [CIAL:						
	thorized to certify non-u						
	Lead			SAMPLI	EDATE		
Cadmium	Mercury	· ·	THE RESERVE THE PERSON NAMED IN	DAY	The same of the sa		
Chromium	Molybdenum		11	05	08		
	Nickel						
Copper	THORET					<u> </u>	
BARAMETER.			COVCENTRATION	Ţ	I CA	MPLE TYPE	
PARAMETER		RESULT	CONCENTRATION THRESHOLD	UNITS		OMP/GRAB	
		RESULT	VALUE EXCEEDED YES OR NO	UNIS			
	Sample Measurement	0.0511		mall			
COPPER	Threshold Value	0.092	n	1	20	comp.	
	Sample Measurement						
	Threshold Value		1617 18 1920				
	Sample Measurement	/2	0 4				
	Threshold Value	27/	W	100			
	Sample Measurement		JAN 2009	251			
14.0	Threshold Value	65	Indiana Series	98/	e .		
	Sample Measurement	15	le.	b/			
	Threshold Value		551-123	302			
	Sample Measurement		100	73			
	Threshold Value		8 1 - 5	\ \(\sigma_{\infty} \)			
	Sample Measurement		100 mg 8	55			
	Threshold Value		100	A 60 60 60 60 60 60 60 60 60 60 60 60 60			
	Sample Measurement		COLON	110			
	Threshold Value		CE 21212 GV	tiercy			
	Sample Measurement						
	Threshold Value						

PVSC Form MR-3 10/96